

General Environmental Incident Summary

Incident: 1578 **Notice:** 12/5/2011 1615 **Occurred:** 12/4/2011 1530

DEM Incident No:

No Further Action: ☒

Responsible Party: Ten Old Transportation

County: Burleigh

Twp Rng Sec Qtr: 139 80 27 NW NW NW

Lat Long + Method: 46.83086 -100.76240 Derived from TRS

Location Description: Occurred just south of the intersection E. Century Ave and State Street in Bismarck (North-bound lane).

Submitted By Info: Shawn MacGillivray

Received By Info: Brad Torgerson

NDDoH

Contact Info: Lynn Kearney

Unknown

Unknown ND

Affected Medium: 02 - water

Near. Occupied Bldg: 300 Feet

Type of Incident: Tank Leak

Release Contained:

Reported to NRC: Yes

Contaminant: Diesel Fuel

Volume of Release: 90 gallons

Duration of Release: 35 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Tractor Trailer operated by Ten Old Transportation collided with a vehicle on State Street wherein the saddle tank of the tractor was punctured causing the release.

Risk Evaluation:

Impacts to water and ice

Potential Env. Impacts:

Spilled diesel fuel entered a storm sewer and diesel fuel has reportedly entered a tributary of Hay Creek

Action Taken/Planned:

A containment bladder was placed beneath the leaking tank. Sand was placed on the street by the Bismarck Fire Department. Sorbant pads are being placed WPC at the exit end of a storm sewer that discharges into a tributary of Hay Creek.

Wastes Disposal Location:

Unknown at this time.

Other Agencies Involved:

Local Fire Department, Local Law Enforcement, Anton Sattler

Updates

Date: 2/1/2012 **Status:** Inspection

Author: Roberts, Kris

Notes:

Western Plains Consulting handled the clean up and recovery of this incident.

Updated Volume: None at the time of this update

Date: 3/1/2012 **Status:** Inspection

Author: Roberts, Kris

Notes:

Western Plains Consulting Final report was received and reviewed around this date. Debris and impacted sediments from the storm sewer outfall were removed and properly disposed of.

Updated Volume: None at the time of this update